




# Power Electronics

# The Synchronous Machine Control



# The PMSM – like the ideal 3-phase load



$$\begin{aligned} & \sqrt{\frac{2}{3}} \left( u_{sa} = R_s \cdot i_{sa} + \frac{d\psi_{sa}}{dt} \right) \\ & + \sqrt{\frac{2}{3}} \cdot e^{j\frac{2\pi}{3}} \cdot \left( u_{sb} = R_s \cdot i_{sb} + \frac{d\psi_{sb}}{dt} \right) \\ & + \sqrt{\frac{2}{3}} \cdot e^{j\frac{4\pi}{3}} \cdot \left( u_{sc} = R_s \cdot i_{sc} + \frac{d\psi_{sc}}{dt} \right) \\ \hline \vec{u}_s &= R_s \cdot \vec{i}_s + \frac{d\vec{\psi}_s}{dt} \end{aligned}$$


# Mathematical Model – Voltage and Current

- The PMSM has:
  - a 3-phase winding, with resistance and inductance
  - A back emf
- It can be described with the same equation as the ideal 3-phase load – in the ROTOR reference frame (x,y)

$$\vec{u}_s = R_s \cdot \vec{i} + L_s \cdot \frac{d\vec{i}}{dt} + j \cdot \omega \cdot L_s \cdot \vec{i} + \vec{e}_s$$

$$\vec{e}_s = j \cdot \omega_{el} \cdot \psi_m$$

$$\vec{u}_s^{xy} = R_s \cdot \vec{i}_s^{xy} + L_s \cdot \frac{d\vec{i}_s^{xy}}{dt} + j\omega_r \cdot (\vec{\psi}_m^{xy} + L_s \cdot \vec{i}_s^{xy})$$




# 3-phase sampled vector control : 4

Components:

$$u_{sx}^*(k) = \left( \frac{L_s}{T_s} + \frac{R}{2} \right) \cdot \left( i_{sx}^*(k) - i_{sx}(k) \right) + \frac{T_s}{\left( \frac{L_s}{R_s} + \frac{T_s}{2} \right)} \cdot \sum_{n=0}^{n=k-1} \left( i_{sx}^*(n) - i_{sx}(n) \right) - \omega_{el} \cdot L \cdot i_{sy}(k)$$
$$u_{sy}^*(k) = \left( \frac{L_s}{T_s} + \frac{R}{2} \right) \cdot \left( i_{sy}^*(k) - i_{sy}(k) \right) + \frac{T_s}{\left( \frac{L_s}{R_s} + \frac{T_s}{2} \right)} \cdot \sum_{n=0}^{n=k-1} \left( i_{sy}^*(n) - i_{sy}(n) \right) + \omega_{el} \cdot L \cdot i_{sx}(k) + e_{sy}(k)$$

# Control in a rotating reference frame

Torque ref  
Speed  
DC link voltage





# PMSM Torque Control

$$\begin{aligned} T &= \vec{\psi}_s \times \vec{i}_s = \psi_{sx} \cdot i_{sy} - \psi_{sy} \cdot i_{sx} = \\ &= (\psi_m + L_{sx} \cdot i_{sx}) \cdot i_{sy} - L_{sy} \cdot i_{sy} \cdot i_{sx} = \\ &= \psi_m \cdot i_{sy} + (L_{sx} - L_{sy}) \cdot i_{sx} \cdot i_{sy} \end{aligned}$$


Lorenz torque

Reluctance torque



$$\vec{u}_s^{xy} = R_s \cdot \vec{i}_s^{xy} + L_s \cdot \frac{d\vec{i}_s^{xy}}{dt} + j\omega_r \cdot \overbrace{(\vec{\psi}_m^{xy} + L_s \cdot \vec{i}_s^{xy})}^{\text{Psis\_vector}}$$

# Simplest, only y-axis current control






$$T = \psi_m \cdot i_{sy} + (L_{sx} - L_{sy}) \cdot i_{sx} \cdot i_{sy}$$



$$\begin{cases} i_{sx}^* = 0 \\ i_{sy}^* = \frac{T^*}{\psi_m} \end{cases}$$

$$\vec{u}_s^{xy} = R_s \cdot \vec{i}_s^{xy} + L_s \cdot \frac{d\vec{i}_s^{xy}}{dt} + j\omega_r \cdot (\vec{\psi}_m^{xy} + L_s \cdot \vec{i}_s^{xy})$$



# Example: Rasmus Andersson's ExSAM



# Torque & Stator Flux Linkage



# Stator Voltage limitation



$$\bar{u}(1,0,0) = \sqrt{\frac{2}{3}} U_{dc} = -\bar{u}(0,1,1)$$

$$\bar{u}(0,1,0) = \sqrt{\frac{2}{3}} U_{dc} \cdot e^{j\frac{2\pi}{3}} = -\bar{u}(1,0,1)$$

$$\bar{u}(0,0,1) = \sqrt{\frac{2}{3}} U_{dc} \cdot e^{j\frac{4\pi}{3}} = -\bar{u}(1,1,0)$$

$$\bar{u}(0,0,0) = 0 = \bar{u}(1,1,1)$$

$$|\vec{u}_s^{xy}| \sqrt{\frac{2}{3}} U_{dc} \cos\left(\frac{\pi}{6}\right)_{\max}$$

$$= \sqrt{\frac{2}{3}} \cdot U_{dc} \cdot \frac{\sqrt{3}}{2} = \frac{U_{dc}}{\sqrt{2}}$$

# Stator Flux Linkage limitation : I

$$\begin{aligned} |\vec{u}_s| &= \sqrt{(R_s \cdot i_{sx} - \omega_{r,el} \cdot L_{sy} \cdot i_{sy})^2 + (R_s \cdot i_{sy} + \omega_{r,el} \cdot (\psi_m + L_{sx} \cdot i_{sx}))^2} \approx \\ &\approx \sqrt{(\omega_{r,el} \cdot L_{sy} \cdot i_{sy})^2 + (\omega_{r,el} \cdot (\psi_m + L_{sx} \cdot i_{sx}))^2} = \\ &= \omega_{r,el} \cdot \sqrt{(L_{sy} \cdot i_{sy})^2 + (\psi_m + L_{sx} \cdot i_{sx})^2} = \\ &= \omega_{r,el} \cdot \sqrt{(\psi_{sy})^2 + (\psi_{sx})^2} = \omega_{r,el} \cdot |\vec{\psi}_s| \leq \frac{U_{dc}}{\sqrt{2}} \end{aligned}$$

$$|\vec{\psi}_s| \leq \frac{U_{dc}}{\omega_{r,el} \cdot \sqrt{2}}$$

## Example:

$$U_{dc} = 600 \text{ [V]}$$


$$p = 6 \text{ [poles]}$$

$$N_{max} = 15000 \text{ [rpm]}$$

$$\omega_{el\_max} = N_{max} \cdot 2 \cdot \pi / 60 \cdot p / 2 = 4712 \text{ [rad/s]} = 750 \text{ [Hz]}$$

$$P_{sis\_min} = U_{dc} / \sqrt{2} / \omega_{el\_max} = 0.09 \text{ [Vs]}$$

# Stator Flux Linkage limitation : II



## Example:

$$U_{dc} = 600 \text{ [V]}$$


$$p = 6 \text{ [poles]}$$

$$N_{max} = 15000 \text{ [rpm]}$$

$$\omega_{el\_max} = N_{max} * 2 * \pi / 60 * p / 2 = 4712 \text{ [rad/s]} = 750 \text{ [Hz]}$$


$$P_{sis\_min} = U_{dc} / \sqrt{2} / \omega_{el\_max} = 0.09 \text{ [Vs]}$$

# Some Simulink




# Current Limitation

*Limited by the  
Converter or Motor*




# So, where do we position the current ... ?

- **Minimize losses !**
- **What losses?**
  - *Resistive losses?*
  - *Iron losses?*
  - *Converter losses?*
  - *Other losses?*



# Resistive losses

- **Losses in the stator winding only**
- **Not frequency dependent**
- **Not temp dependent**




# Resistive losses, Torque & Flux

Max  
Current


Constant  
Torque

Constant Flux  
linkage




# Find the best operating points ...

- **At low speed**
  - *Minimal current for minimal resistive losses*
- **In Voltage limitation**
  - *Follow constant torque until max current*
- **In Current limitation**
  - *Drop torque to respect the voltage limit*




# Repeat the search ...

- For all possible Torque levels
- For all possible flux levels
- In doing so, for each combination:
  - *always select the lowest resistive losses*
  - *Always respect the current limit*



# The drive system performance

- **With the current references known for all torque levels and all flux levels:**
- **For each speed and torque combination:**
  - *Find the Stator flux linkage limit for each speed.*
  - *Select the best currents for the torque & speed combination*
  - *Calculate the losses and limitations in torque*
  - *Plot the Torque Speed Characteristic efficiency etc*




# But, there are more than resistive losses ...

e.g.

- **Iron losses**  
– Here modelled as




$$P_{fe} = k \cdot (\omega_{r,el} \cdot |\vec{\psi}_s|)^2$$

- **Converter losses**






# Do you remember the Converter Efficiency ... ?

$f_{SW} = 1000 \ 3000 \ 10 \ 000 \text{ Hz}, \cos(\varphi) = 1$




$f_{SW} = 3000 \text{ Hz}, \cos(\varphi) = 0 \ 0.25 \ 0.5 \ 0.75 \ 1$



Modul-3: Motor control for maximum efficiency


# Introduce the new losses, and do it all again ...



# Find the best operating points ...



## This time:

- *OPTIMAL currents for minimal total losses*
- *Speed differentiates*
  - *Iron losses and Converter losses are speed or voltage dependent*



# Repeat the search ...


- For all possible Torque levels
- For all possible flux levels
- For several different speeds
- In doing so, for each combination:
  - always select the lowest TOTAL losses
  - Always respect the current limit



[rpm] :  
15 000  
12 000  
9 000  
6 000  
3 000


# The drive system performance

- **With the current references known for all torque levels and all flux levels:**
- **For each speed and torque:**
  - *Find the Stator flux linkage limit for each speed.*
  - *Select the best currents for the torque & speed combination*
  - *Calculate the losses and limitations in torque*
  - *Plot the Torque Speed Characteristic, efficiency etc*




# This is the energy optimal drive control !



- It accounts for all losses
- At all possible speed and torque combinations
- ... but we can do more with this information!







# Conclusions

- **A good control system for a PMSM requires:**
  - A Current Controller, either a *PIE + Modulator* OR a *Tolerance Band* controller
  - A field weakening controller.
- **The proposed field weakening controller is an extension of a loss minimisation strategy:**
  - Set the current references for lowest *TOTAL losses* (including resistive, inductive and converter losses)
  - When needed, respect the maximum flux limitation and try to keep the torque up.
  - Respect also the current limit and reduce torque if needed.
- **The same data that is the base for control is also useful as base for modelling**









# End of the PMSM story